

FOX-O-RING mode SW8=off

MORSE CHARACTER (A - Z)

DAH	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	1	2	3	4	5
DIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

ON-TIME(secs) per 1 min cycle

<input type="checkbox"/>	<input type="checkbox"/>	ON (1)
6	7	
<input type="checkbox"/>	<input type="checkbox"/>	OFF(0)

<input type="checkbox"/>	8	OFF
<input checked="" type="checkbox"/>		

0	0	60 (ie. continuous)
1	0	30 (recommended)
0	1	20
1	1	15

n.b.
The **last** right-most switch set to **ON**, is treated as the end-of-character marker.
e.g.

A = 01**1**00

<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1	2	3	4	5
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

D = 100**1**0

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
1	2	3	4	5
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

nb.1-5 ALL-OFF will give on/off keying.

MO mode SW8=on

TX No. (MO?)

ON (1)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	1	2	3	
OFF(0)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
1	0	0	0	MOe
2	1	0	0	MOi
3	0	1	0	MOs
4	1	1	0	MOh
5	0	0	1	MO5
6	1	0	1	MO n
7	0	1	1	MO d
8	1	1	1	MO b

NO. OF FOXES

ON (1)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	4	5	6
OFF(0)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
MO	0	0	0
2	1	0	0
3	0	1	0
4	1	1	0
5	0	0	1
6	1	0	1
7	0	1	1
8	1	1	1

MAX. ON-TIME & CYCLE-TIME

<input type="checkbox"/>	30secs / 2mins	<input checked="" type="checkbox"/>	ON
7			
<input type="checkbox"/>	60secs / 5mins	<input type="checkbox"/>	

n.b. SW-7
On and cycle times are **maximum** times.
e.g. for 30secs / 2mins setting.

Cycle time will be less than 2 mins if the number of foxes is less than 4.

On time will be less than 30secs if the number of foxes is greater than 4.